

Setup IE for recorder

Installation preparations

1.Connect the camera with Local network, power the camera (DC12V power supply or Power over Ethernet if support).Use default IP address 192.168.1.10 to access the camera, or get IP address through upgrade tool “DeviceManage.exe” software.

Mark: Please contact supplier to get DeviceManage software. Or download from


<https://www.e-cylinderiot.com/download/>






First time login the web need install activeX plug, if your computer have not link to internet , you can download and install activeX plug “New active.exe” from

<https://www.e-cylinderiot.com/download/>.


2.Login camera web by IE enter user name: admin and default password is null (if you modify the password please enter correct password), click login enter camera preview page . select “Device cfg>Setting>System>GUI display”, enable region cover you can setup 4 masking click masking number and click setting enter picture move the mask bold to you want masking area click “ok” to save and exit.

2.1If you already install ActiveX plug and enter camera IP address by IE can not see login page or have not see ActiveX plug install prompt, you need enable the run ActiveX and run script option on Internet Explorer, see below operate pictures. Open IE browser find “tools>Internet options>Security” item select “Custom level” button enter new item setting, slide down find “ActiveX controls and plug-ins” item enable the 1‘Allow ActiveX filtering’ 2‘Download signed ActiveX controls’ 3‘Run ActiveX controls and plug-ins’ 4‘Run antimalware software on ActiveX controls’ 5‘Script ActiveX controls marked safe for scripting’ continue slide down find “Downloads” enable the ‘File download’ and slide down find “Scripting” item and enable ‘Active scripting’. click “ok” to save and exit.









1. Search the camera IP address by tool



2. Login camera web by IE and install plug





Select language and click “next” “next” “next” button and finished installation. Then refresh the IE will show “login” button. If still have not see login button suggest your restart computer then login by IE enter user name: admin and default password is null (if you modify the password please enter correct password), click login enter camera live page.

